The Windows Driver Installation

 Navigate to the Driver\Windows directory and double-click on the 'XPrinter Driver v8.2.exe' file. An installation window will appear. The software will automatically detect your computer's system, so manual selection is not required. If the printer uses a USB interface, set the Printer Series to XP80-C. Before proceeding to the next step, click on "Check USB Port" to automatically detect the port used by the printer on your computer. Note down this port number.

Install Configuration	×	
Xprinter。总择	You are using Windows 11 x64 OS. Please select Windows 11 to install. Select Windows OS © Windows XP © Windows 2003 © Windows 8/8.1 © Windows 7 © Windows 10 © Windows 11	
	Printer Interface : USB O Oth XPrinter Driver V8.2 Select Printer Series O XP-58 O XP-58C VSB004 Vour USB printer's USB004	; Port is :
	C XP-76 C XP-76C	ок
	Set Default Printer	
http://www.xprinter.net	Check USB Port Install Now EXIT	

2. Click on the "Install Now" button to begin the installation of the printer driver.

3. After successful installation, in the dialog box confirming the successful driver installation, click the "Yes" button to open the printer's properties dialog. Click on the "Print Test Page" button. If the printer prints a test page, it indicates that the driver has been successfully installed. If not, you need to specify the virtual USB port for the printer: Click on the "Port" tab on the window, then select the port detected by the installation program in the first step (e.g., USB004), and click the "Apply" button. Return to the "General" tab, then click "Print Test Page" again.

tall Configurati	on			
Xprinter [®]	论样 (Printer Driver	You are using Windows : Please select Windows 1 Select Windows OS C Windows XP C Windows 2003 V8.2	11 x64 OS. 1 to install. O Window O Window	s Vista s 8/8.1 10
		Ceed ! you want to configure pr Yes C XP-76 *Remarks: "C" means Set Default Printer	No C XP-76C item with cutter	her
ttp://www.xp	rinter.net	Check USB Port	Install Now	EXIT
General Sharin	perties	vanced Color Manageme	ent Security D) Device Settings
General Sharin	perties g Ports Ad -80C	vanced Color Manageme s). Documents will print	ent Security D	> Vevice Settings
General Sharin General Sharin XP Print to the fc checked port. Port FILE: WSD-2 USB001 VERDED	Porties g Ports Ad -80C Ad -80C Description Print to File WSD Port WSD Port Virtual printe	vanced Color Manageme s). Documents will print Printer NPIDFCC6 NPIACAAE	ent Security D to the first free iF (HP LaserJet 1 B5 (HP LaserJet	Vevice Settings
General Sharin Ceneral Sharin Cenera	Porties g Ports Ad -80C Ad -80C Description Print to File WSD Port WSD Port WSD Port Virtual printe Virtual printe Virtual printe PrinterPOS-8	vanced Color Manageme s). Documents will print printer Printer NPIDFCC6 NPIACAAE er port for er port for ar port for 20 XP-80C	ent Security D to the first free iF (HP LaserJet 1 B5 (HP LaserJet	Vevice Settings
General Sharin Ceneral Sharin Print to the for checked port. Port FILE: WSD-9 USB001 USB002 USB003 USB004 Add Po	Porties Ports Ad -80C -80C	vanced Color Manageme s). Documents will print Printer NPIDFCC6 NPIACAAE er port for er port for 30 XP-80C Delete Port	ent Security D to the first free iF (HP LaserJet 1 B5 (HP LaserJet	VI15w) MFP
General Sharin General Sharin XP Print to the for checked port. Port FILE: WSD-2 WSD-2 USB001 USB002 USB003 USB004 Add Port Enable bid Enable print	Porties Ports Ad -80C -80C Ad -80C -80	vanced Color Manageme s). Documents will print Printer NPIDFCC6 NPIACAAE er port for er port for 30 XP-80C Delete Port port	ent Security D to the first free SF (HP LaserJet 1 B5 (HP LaserJet Configu	VI15w) MFP

Note: If the printer prints a test page, it confirms the successful installation of the driver.